## North America Emission Control Area Fuel Oil Non-Availability Report
## ECA0100
## 1 2 3
##

##(Include Double Pound for comments not form fields)
##Report Form ID Ship Operator Name Oldendorff Carriers CAPETAN COSTIS

4 5 6 7

Flag Country IMO ID Number Date of ECA First Notice Location of ECA First Notice ITALIAN 9520637 23-May-13 JINZHOU, CHINA

Name of Ports after First Notice Name of Last Port before ECA Entry Name of Port with Fuel Oil Supply Disruption HAWK INLET, ALASKA JINZHOU, CHINA

11 12 13

Name of Original Fuel Supplier with Disruption Number of Fuel Suppliers Contacted Date of Entry in the ECA 7-Jun-13

Time of Entry in the ECA Sulfur Content of Non-Compliant Fuel Oil Projected Hours on Main Propulsion 0000 LT 3.24% 72 hrs

Name of First POC Compliance Fuel Oil Available at First POC? Plan to Bunker Compliant Fuel Oil at First POC? **Yes** Yes

Number of fuel suppliers contacted at First POC Name of Second POC Compliant Fuel Oil at Second POC?

1+ n/a n/a

23 24

Plan to Bunker Compliance Fuel Oil at Second POC? Number of Fuel Suppliers Contacted at the Second POC? n/a n/a

25 26 27

Date of Exit from ECA? Time of Exit from ECA? Has this vessel operated in the ECA in previous 12 months? ABT 26 JUNE abt 1600 lt yes

Number of Separate Visits to the ECA Number of Ports visited in the ECA Previously submitted ECA0100 forms? 
1 no

Number of Submitted Reports Designated Corporate Official Name Designated Corporate Official E-mail

Designated Corporate Official Phone Number

Description of Actions to Achieve Compliance
vessel sailed jinzhou china with 72 mts compliant Isfo on board
same sufficient for intended voyage into intended loadport vancouver, bc
voyage plan changed after sailing
new voyage loadport rotation changed to hawk inlet-stewart, bc - vancouver, bc
vessel consumed Isfo during entry into eca zone but supply ran out at hawk inlet
vessel forced to switch to consume regular ifo until arrival at vancouver, bc where Isfo will be replenished